

MAIN MENU

VIDEO FORMAT

◀ 2M25 ▶

EXPOSURE

↵

DAY/NIGHT

↵

VIDEO SETTINGS

↵

FUNCTIONS

↵

FACTORY DEFAULT

↵

EXIT

↵

SAVE&EXIT

↵

EXPOSURE

EXPOSURE MODE	◀ GLOBAL ▶
AGC	◀ LOW ▶
SLOW SHUTTER	◀ OFF ▶
BACK	↵
EXIT	↵
SAVE&EXIT	↵

EXPOSURE

EXPOSURE MODE	◀ B L C ▶
AGC	◀ L O W ▶
S L O W S H U T T E R	◀ O F F ▶
B A C K	↵
E X I T	↵
S A V E & E X I T	↵

EXPOSURE

EXPOSURE MODE	◀ H L C ▶
AGC	◀ L O W ▶
S L O W S H U T T E R	◀ O F F ▶
B A C K	↵
E X I T	↵
S A V E & E X I T	↵

EXPOSURE

EXPOSURE MODE ◀ WDR ▶

AGC ◀ LOW ▶

SLOW SHUTTER ◀ OFF ▶

BACK ↵

EXIT ↵

SAVE&EXIT ↵

DAY/NIGHT

MODE	◀ AUTO ▶
IR LIGHT	◀ ON ▶
SMART IR	◀ MODE 1 ▶
LEVEL	◀ 1 ▶
D -> N THRESHOLD	◀ 5 ▶
N -> D THRESHOLD	◀ 5 ▶
BACK	↵
EXIT	↵
SAVE&EXIT	↵

DAY/NIGHT

MODE

◀ COLOR ▶

BACK

↵

EXIT

↵

SAVE&EXIT

↵

DAY/NIGHT

MODE

◀ B & W ▶

IR LIGHT

◀ ON ▶

SMART IR

◀ MODE 1 ▶

LEVEL

◀ 1 ▶

BACK

↵

EXIT

↵

SAVE & EXIT

↵

VIDEO SETTINGS

IMAGE MODE	◀ STD ▶
WHITE BALANCE	↵
BRIGHTNESS	◀ 5 ▶
CONTRAST	◀ 5 ▶
SHARPNESS	◀ 5 ▶
SATURATION	◀ 5 ▶
3DNR	◀ 6 ▶
MIRROR	◀ OFF ▶
BACK	↵
EXIT	↵
SAVE&EXIT	↵

VIDEO SETTINGS

IMAGE MODE	◀ HIGH - SAT ▶
WHITE BALANCE	↵
BRIGHTNESS	◀ 7 ▶
CONTRAST	◀ 5 ▶
SHARPNESS	◀ 5 ▶
SATURATION	◀ 9 ▶
3DNR	◀ 6 ▶
MIRROR	◀ OFF ▶
BACK	↵
EXIT	↵
SAVE&EXIT	↵

WHITE BALANCE

MODE	◀ AUTO ▶
BACK	↵
EXIT	↵
SAVE&EXIT	↵

WHITE BALANCE

MODE	◀ MANUAL ▶
R-GAIN	◀ 81 ▶
B-GAIN	◀ 88 ▶
BACK	↵
EXIT	↵
SAVE&EXIT	↵

FUNCTIONS

MOTION DET	↵
PRIVACY	↵
BACK	↵
EXIT	↵
SAVE&EXIT	↵

MOTION DET

MODE	◀ OFF ▶
AREA 0	↵
AREA 1	↵
AREA 2	↵
AREA 3	↵
SENSITIVITY	◀ 50 ▶
COLOR	◀ RED ▶
TRANSPARENCY	◀ OFF ▶
BACK	↵
EXIT	↵
SAVE&EXIT	↵

AREA 0

DISPLAY	◀ OFF ▶
X POSITION	◀ 13 ▶
Y POSITION	◀ 6 ▶
WIDTH	◀ 30 ▶
HEIGHT	◀ 33 ▶
BACK	↵
EXIT	↵
SAVE&EXIT	↵

PRIVACY

MODE	◀ OFF ▶
AREA 0	↵
AREA 1	↵
AREA 2	↵
AREA 3	↵
COLOR	◀ RED ▶
TRANSPARENCY	◀ OFF ▶
BACK	↵
EXIT	↵
SAVE&EXIT	↵

AREA 0

DISPLAY

◀ OFF ▶

X POSITION

◀ 13 ▶

Y POSITION

◀ 6 ▶

WIDTH

◀ 30 ▶

HEIGHT

◀ 33 ▶

BACK

↵

EXIT

↵

SAVE&EXIT

↵